#### CERCLA REMOVAL ACTION DAILY WORK ORDER

SITE NAME: BCF OIL REFINING

CONTRACT NO. 68-S2-99-07

ORDER NO.: 19

SITE/SPILL NO.: PU EPA REGION: II

DATE(s): 3/28/01 SHIFT:0700 - 1730 OSC: Thomas P.Budroe

CONTRACTOR: WRS Infras.& Env., Inc. MONITORS: Paul Potvin

WORK ORDER #95 RM: Bob Moody

## DESCRIPTION OF WORK TO BE PERFORMED

1) Provide form 1900-55s to the OSC for approval.

2) Provide security for the Site from 3:30pm until 7:30am the following morning. One person acting as the guard will be on-site at all times. Each guard will key-in at the appropriate time and location at each key-box. The guard will periodically inspect the site for any releases, spills, leaks, fires, etc.

3) Conduct daily safety briefing.

- 4) Complete a Daily Work Summary outlining daily accomplishments.
- 5) Obtain waste delivery confirmation from Safety Kleen and provide same to EPA.
- 6) Bulk the residual tank materials of the same waste stream into one tank then pump the aqueous phase into the oil water
- 7) Remove all liquid wastes from tank 16 and stabilize the sludge.
- 8) Cover the opening in tank 16 at the end of the working day so that it prohibits precipitation from entering tank 16 if precipitation is anticipated prior to the start of the next working day.
- 9) Sample tanks 2,3,6,7 the rolloff, the cart in the shaker house and the box screen and analyze for PCBs with a one week turnaround time and a data package that can be data validated.
- 10) Obtain and load a rolloff or other appropriate container with the uncontaminated scrap steel on Site and ship off-site for recycling.
- 11) Remove the steam coils (pipes) from tanks 11, 12 and 17.
- 12) Secure three bids for clean backfill to be used to backfill underground tanks.
- 13) Obtain two loads of stone and cover the area of ground above backfilled tank 15.

# NUMBER OF PERSONNEL AUTHORIZED

1-RESPONSE MANAGER 0-FOREMAN 3-CLEANUP TECHNICIAN(S) 1-PCT <u>0-CHEMIST 1-EQUIPMENT OPERATOR</u> 0-LAB TECH 0-T&D Coordinator EQUIPMENT AND EXPENDABLE MATERIALS AUTHORIZED

#### ITEM OUANT. ITEM OUANT. PICK UP TRUCK (1/4 TON) 3 FAX 1 RADIO HAND HELD 3 CELLULAR TELEPHONE 1 **EXCAVATOR** 1 2 LAPTOP COMPUTER PORTABLE BOILER 0 COMPUTER PRINTER 2 DOUBLE DIAPHRAGM PUMP

I CERTIFY THAT THE ABOVE WORK IS ORDERED AND AUTHORIZED BY THE CONTRACTOR IN THE PERFORMANCE OF THE ABOVE CITED DELIVERY ORDER

1

SIGNATURE OF ON-SCENE COORDINATOR

Crawe D. Arediae

SIGNATURE OF CONTRACTOR'S REPRESENTATIVE I ACKNOWLEDGE RECEIPT OF THIS WORK ORDER.

AIR COMPRESSOR

### CERCLA REMOVAL ACTION DAILY WORK ORDER

SITE NAME: BCF OIL REFINING ORDER NO.: 19	CONTRACT NO. 68-S2-99-07 DATE(s): 3/28/01
SITE/SPILL NO.: PU	SHIFT:0700 - 1730
EPA REGION: II	OSC: Thomas P.Budroe
CONTRACTOR: WRS Infras.& Env., Inc.	WORK ORDER #95
MONITORS: Paul Potvin	RM: Bob Moody
MONITORS. FAUL FOCVIII	KM; BOD MOODY
DESCRIPTION OF SUPPLIES	REQUIRED
•	
Amendments:  OSC aucherize In. Di Cicco and P. Musshutty to work butil 1860 aus.	
to work entil 1860 aus.	
	•
	· · · · · · · · · · · · · · · · · · ·
SIGNATURE OF ON-SCENE COORDINATOR	un sullie
	_
SIGNATURE OF CONTRACTOR'S REPRESENTATIV	re lywd
	1

Page 2